



Capital City Nissan Of Topeka



Automobile Status Report

Prepared For



INVENTORY: 9455P

2018 Toyota COROLLA iM

Date April 23, 2024

VIN JTNKARJE5JJ556557

Mileage 143073

RO# 6075234



Service Advisor

KYLE MCELWEE

kylemc.nissan@gmail.com

7852676700



Capital City Nissan Of Topeka

1980 Sw Topeka Blvd

Topeka, KS 66612

Capital City Nissan Of Topeka Service Commitment

Excellence at every turn... and every straightaway

Our dealership's primary goal is to satisfy every customer at every opportunity. You visit our service department regularly, and we have developed a number of ways to make your visit more comfortable and informative. We know that you want straight answers, and that's the only way we will deliver it to you.

We understand that your knowledge of your vehicle and its necessary repairs is probably not on par with the understanding that your technician has. In order to be sure that his findings and reporting is as clear and concise as possible, we use this Vehicle Information Booklet as a tool to help us communicate your vehicle's condition to you.

Our technicians are the most qualified to work on your vehicle. They have trained extensively, and partake in continuing education regularly to be sure that they are up to date on any changes and improvements handed down from the manufacturer. Our service advisors strive to make your experience with us a pleasant one. They are here to attend to your automotive needs as well as communicate effectively between your technician and you.

Please make yourself comfortable in our waiting area. Watch some TV, use your laptop with our free WI-FI access or just relax and enjoy the quiet. Our courtesy shuttle can take you shopping, to a movie or home if you prefer.

We appreciate your business and will continue to strive for excellence in everything we do for you.



Complimentary Multi-Point Inspection

RO# 6075234

INVENTORY: 9455P

VIN JTNKARJE5JJ556557

Advisor KYLE MCELWEE

Technician Ezequiel Marquez

Created On 4/23/2024

Checked and OK at this time

May Require Future Attention

Requires immediate attention

ROAD TEST

- BRAKE OPERATION PASS
- ENGINE OPERATION PASS
- DRIVETRAIN OPERATION PASS
- TRANSMISSION OPERATION PASS

LIGHTS

- TAIL LAMPS PASS
- HEAD LAMPS PASS
- STOP LAMPS PASS
- TURN SIGNALS PASS
- SIDE MARKER LAMPS PASS
- LICENSE PLATE LAMPS PASS
- EMERGENCY FLASHERS PASS

UNDER HOOD

- BLOCK TEST PASS
- OIL CHANGE PASS
- STEERING LINKS PASS
- FLUID AT LEVELS PASS


FUNCTIONAL


- HORN PASS
- TIRES PASS
- LF g
- RF g
- LR g
- RR g
- SEAT BELTS PASS
- WINDSHIELD PASS
- PARKING BRAKE PASS
- WIPERS AND WASHERS PASS
- HEATER AND DEFROSTER PASS
- OIL STICKER, ALL VALVE STEM CAPS AND ALL MAINTENANCE LIGHTS RESET PASS
- BRAKE PAD MEASUREMENTS PASS
- LF z
- RF z
- LR z
- RR z



Additional Service Recommendations

In the process of inspecting your vehicle for safety and reliability, your technician **Ezequiel M** made the following observations and recommends that you do the necessary repairs to resolve these issues.

 Red: requires immediate attention.

 Yellow: in need of attention soon.

Air Filter: due every 105,000 miles

Item Description

Your Air Filter should be inspected at each service interval and replaced every other oil change or after 12 months.

Your air filter may need replacement if:

- There are visible signs of dirt, dust, etc.
- You experience a decrease in MPG

Your air filter traps dust and debris so that it does not get into the intake system and potentially damage the engine. A dirty air filter prevents the necessary volume of clean air from reaching the engine reducing your MPG.

Reason



Cabin Filter & In-Cabin Micro Filter: DUE EVERY 15,000MILES

Item Description

Your Cabin Filter and In-Cabin Micro Filter should be inspected at each service and replaced every other oil change or after 12 months.

Your cabin and in-cabin micro filter may need replacement if:

- Your heating and cooling system has reduced airflow or there are bad odors or a musty smell
- There are visible signs of dirt, dust or other pollutants

Reason

The cabin filter / in-cabin microfilter function like your furnace filter at home. They clean the air by trapping pollen, bacteria, dust and exhaust gases



that may find their way into a vehicle's HVAC system. Dirty filters reduce your heating and cooling efficiency

Front Wipers: recommend replacing both front wiper blades due to the blad splitting

Item Description

Your Wipers should be inspected at each service interval and replaced when indicated.

Indicators shock replacement may be needed are:

- If blades are cracked, become misshapen or lose their flexibility
- If they do not wipe properly

Replacing your wiper blades when recommended enhances safety, increases visibility and reduces the chance of damage to your windshield.

Reason

***Windshield Wiper Blade - (Rear): recommend replacing rear wiper blade due to the balde splitting**

Item Description

Many vehicles are equipped with rear wipers; most commonly, sport utility vehicles, hatchbacks and station wagons. The rear wiper allows the driver to have visibility through the rear window. This is important during bad weather or dirty conditions.

Reason

The rear windshield wiper will need to be replaced occasionally. When you notice the wiper streaking on the glass or becoming worn, remove it immediately and have it properly replaced.

Tire Repair: passenger rear tire has a nail and it is repairable

Item Description

This is work necessary to fix a damaged or flat tire.



Reason

If not repaired, a damaged or flat tire will not ride properly due to deflation, puncture or other damage. This can prevent the vehicle from riding properly and comfortably.



Completed Repairs

PREPARED FOR
INVENTORY: 9455P

Service Advisor
KYLE MCELWEE (737)
kylemc.nissan@gmail.com

Date 04/23/2024 08:03 AM
2018 TOYOTA COROLLA iM
VIN JTNKARJE5JJ556557
Mileage 143,073
RO# 6075234

Service Name	Price
Air Filter: due every 105,000 miles (I)	\$28.99
Cabin Filter & In-Cabin Micro Filter: DUE EVERY 15,000MILES (I)	\$41.29
Front Wipers: recommend replacing both front wiper blades due to the blad splitting (I)	\$43.98
*Windshield Wiper Blade - (Rear): recommend replacing rear wiper blade due to the balde splitting (I)	\$18.49
Tire Repair: passenger rear tire has a nail and it is repairable (I)	\$16.95
Printed on April 23, 2024	
Quote expires on May 23, 2024	

Subtotal	\$149.70
Shop Charges	\$4.57
Tax	\$14.42
Total	\$168.69



Capital City Nissan Of Topeka
1980 Sw Topeka Blvd
Topeka, KS 66612

(785)267-6700