



Capital City Nissan Of Topeka



Automobile Status Report

Prepared For



INVENTORY: 9458P

2015 Kia FORTE KOUP

Date April 24, 2024

VIN KNAFX6A88F5357884

Mileage 87059

RO# 6075275



Service Advisor

Chris Howard

ckhoward785@gmail.com



Capital City Nissan Of Topeka
1980 Sw Topeka Blvd
Topeka, KS 66612

Capital City Nissan Of Topeka Service Commitment

Excellence at every turn... and every straightaway

Our dealership's primary goal is to satisfy every customer at every opportunity. You visit our service department regularly, and we have developed a number of ways to make your visit more comfortable and informative. We know that you want straight answers, and that's the only way we will deliver it to you.

We understand that your knowledge of your vehicle and its necessary repairs is probably not on par with the understanding that your technician has. In order to be sure that his findings and reporting is as clear and concise as possible, we use this Vehicle Information Booklet as a tool to help us communicate your vehicle's condition to you.

Our technicians are the most qualified to work on your vehicle. They have trained extensively, and partake in continuing education regularly to be sure that they are up to date on any changes and improvements handed down from the manufacturer. Our service advisors strive to make your experience with us a pleasant one. They are here to attend to your automotive needs as well as communicate effectively between your technician and you.

Please make yourself comfortable in our waiting area. Watch some TV, use your laptop with our free WI-FI access or just relax and enjoy the quiet. Our courtesy shuttle can take you shopping, to a movie or home if you prefer.

We appreciate your business and will continue to strive for excellence in everything we do for you.



Complimentary Multi-Point Inspection

RO# 6075275

INVENTORY: 9458P

VIN KNAFX6A88F5357884

Advisor Chris Howard

Technician Scott Dixon

Created On 4/24/2024

Checked and OK at this time

May Require Future Attention

Requires immediate attention

ROAD TEST

- BRAKE OPERATION PASS
- ENGINE OPERATION PASS
- DRIVETRAIN OPERATION PASS
- TRANSMISSION OPERATION PASS

LIGHTS

- TAIL LAMPS PASS
- HEAD LAMPS PASS
- STOP LAMPS PASS
- TURN SIGNALS PASS
- SIDE MARKER LAMPS PASS
- LICENSE PLATE LAMPS PASS
- EMERGENCY FLASHERS PASS

UNDER HOOD

- BLOCK TEST PASS
- OIL CHANGE PASS
- STEERING LINKS PASS
- FLUID AT LEVELS PASS

FUNCTIONAL

- HORN PASS
- TIRES PASS
- LF 6
- RF 7
- LR 9
- RR 9
- SEAT BELTS PASS
- WINDSHIELD PASS
- PARKING BRAKE PASS
- WIPERS AND WASHERS FAIL
- HEATER AND DEFROSTER PASS
- OIL STICKER, ALL VALVE STEM CAPS AND ALL MAINTENANCE LIGHTS RESET PASS
- BRAKE PAD MEASUREMENTS PASS
- LF 5
- RF 5
- LR 1
- RR 1



Additional Service Recommendations

In the process of inspecting your vehicle for safety and reliability, your technician **Scott D** made the following observations and recommends that you do the necessary repairs to resolve these issues.

Red: requires immediate attention.

Yellow: in need of attention soon.

Wiper Blade Replacement: wiper blades streak

Item Description

The wiper blade is a rubber blade attached to the end of the wiper arm.

Reason

If not replaced, worn out wiper blades can cause restricted visibility and permanent damage to the windshield.



Windshield Wiper Blade

Engine Air Filter Replacement: air filter dirty

Item Description

The air filter prevents dirt and debris from entering the engine, which could otherwise cause premature engine wear.

Reason

If not replaced, poor gas mileage and premature engine wear will result.



Air Filter

Brake Job - Replace Front Brake Pads and Resurface Rotors: rear brakes are at 1mm

Item Description

Brake pads are the parts of a car's braking system that actually take the brunt of the frictional force necessary to stop the car. In a disc brake system, the brake pedal activates a hydraulic line which squeezes calipers against the rotors of the car's tires. Brake pads are positioned between the



calipers and the rotors to absorb the energy and heat, and then provide enough grip to stop the car. Brake pad material wears out over time. Brake pads should be periodically inspected for wear, which is highly variable depending on vehicle weight and driver habits.

Reason

Brake pads must be replaced before the friction material is worn away completely. If it isn't, metal-to-metal contact will occur between the brake rotor and the worn-out brake pad. If metal-to-metal contact occurs, the brake rotor will be damaged, and it will need to be resurfaced or replaced. When the pads are replaced, the rotor must be resurfaced smooth to allow the new pads to have an even contact surface to work with. Only a small amount of material can be machined off of a rotor before it becomes unusable and must be replaced.

Rotate tires: based on tread depths

Item Description

Our certified technician will perform a tire rotation on your vehicle. Tire rotations are crucial for even tire wear and longevity.

Reason

If damaged or malfunctioning the transmission will not shift properly, and in most cases it will not shift at all. This can potentially damage the transmission and engine as well as decrease fuel economy,.



Completed Repairs

PREPARED FOR
INVENTORY: 9458P

Service Advisor
Chris Howard (454)
ckhoward785@gmail.com

Date 04/24/2024 08:02 AM
2015 Kia FORTE KOUP
VIN KNAFX6A88F5357884
Mileage 87,059
RO# 6075275

| Service Name | Price |
|---|----------|
| Wiper Blade Replacement: wiper blades streak (l) | \$42.88 |
| Engine Air Filter Replacement: air filter dirty (l) | \$26.99 |
| Brake Job - Replace Front Brake Pads and Resurface Rotors: rear brakes are at 1mm (l) | \$295.90 |
| Rotate tires: based on tread depths | \$19.95 |
| Printed on April 24, 2024 | |
| Quote expires on May 24, 2024 | |

| | |
|--------------|-----------------|
| Subtotal | \$385.72 |
| Shop Charges | \$30.00 |
| Tax | \$38.87 |
| Total | \$454.59 |



Capital City Nissan Of Topeka
1980 Sw Topeka Blvd
Topeka, KS 66612

(785)267-6700