



## Capital City Nissan Of Topeka

# Automobile Status Report

Prepared For

INVENTORY: 402569A



2018 Nissan ALTIMA

**Date** May 08, 2024

**VIN** 1N4AL3AP7JC153103

**Mileage** 137466

**RO#** 6075646



Service Advisor

Chris Howard

ckhoward785@gmail.com



**Capital City Nissan Of Topeka**

1980 Sw Topeka Blvd

Topeka, KS 66612

# Capital City Nissan Of Topeka Service Commitment

## Excellence at every turn... and every straightaway

Our dealership's primary goal is to satisfy every customer at every opportunity. You visit our service department regularly, and we have developed a number of ways to make your visit more comfortable and informative. We know that you want straight answers, and that's the only way we will deliver it to you.

We understand that your knowledge of your vehicle and its necessary repairs is probably not on par with the understanding that your technician has. In order to be sure that his findings and reporting is as clear and concise as possible, we use this Vehicle Information Booklet as a tool to help us communicate your vehicle's condition to you.

Our technicians are the most qualified to work on your vehicle. They have trained extensively, and partake in continuing education regularly to be sure that they are up to date on any changes and improvements handed down from the manufacturer. Our service advisors strive to make your experience with us a pleasant one. They are here to attend to your automotive needs as well as communicate effectively between your technician and you.

Please make yourself comfortable in our waiting area. Watch some TV, use your laptop with our free WI-FI access or just relax and enjoy the quiet. Our courtesy shuttle can take you shopping, to a movie or home if you prefer.

We appreciate your business and will continue to strive for excellence in everything we do for you.



# Complimentary Multi-Point Inspection

RO# 6075646  
INVENTORY: 402569A  
VIN 1N4AL3AP7JC153103

Advisor Chris Howard  
Technician CODY MILLER  
Created On 5/8/2024

Checked and OK at this time

May Require Future Attention

Requires immediate attention

ROAD TEST			
			BRAKE OPERATION <u>PASS</u>
			ENGINE OPERATION <u>PASS</u>
			DRIVETRAIN OPERATION <u>PASS</u>
			TRANSMISSION OPERATION <u>PASS</u>
LIGHTS			
			TAIL LAMPS <u>PASS</u>
			HEAD LAMPS <u>PASS</u>
			STOP LAMPS <u>PASS</u>
			TURN SIGNALS <u>PASS</u>
			SIDE MARKER LAMPS <u>PASS</u>
			LICENSE PLATE LAMPS <u>PASS</u>
			EMERGENCY FLASHERS <u>PASS</u>
UNDER HOOD			
			BLOCK TEST <u>PASS</u>
			OIL CHANGE <u>PASS</u>
			STEERING LINKS <u>PASS</u>
			FLUID AT LEVELS <u>PASS</u>

FUNCTIONAL			
			HORN <u>PASS</u>
			TIRES <u>PASS</u>
			LF <u>ℓ</u>
			RF <u>ℓ</u>
			LR <u>ℓ</u>
			RR <u>ℓ</u>
			SEAT BELTS <u>PASS</u>
			WINDSHIELD <u>PASS</u>
			PARKING BRAKE <u>PASS</u>
			WIPERS AND WASHERS <u>PASS</u>
			HEATER AND DEFROSTER <u>PASS</u>
			OIL STICKER, ALL VALVE STEM CAPS AND ALL MAINTENANCE LIGHTS RESET <u>PASS</u>
			BRAKE PAD MEASUREMENTS <u>PASS</u>
			LF <u>ℓ</u>
			RF <u>ℓ</u>
			LR <u>ℓ</u>
			RR <u>ℓ</u>



# Additional Service Recommendations

In the process of inspecting your vehicle for safety and reliability, your technician **CODY M** made the following observations and recommends that you do the necessary repairs to resolve these issues.

**Red:** requires immediate attention.

**Yellow:** in need of attention soon.


## Engine Air Filter Replacement

### Item Description

The air filter prevents dirt and debris from entering the engine, which could otherwise cause premature engine wear.

### Reason

If not replaced, poor gas mileage and premature engine wear will result.



Air Filter

## Cabin Filter & In-Cabin Micro Filter: recommended every 15,000 for that clean and fresh air can flow through the hvac system

### Item Description

Your Cabin Filter and In-Cabin Micro Filter should be inspected at each service and replaced every other oil change or after 12 months.

Your cabin and in-cabin micro filter may need replacement if:

- Your heating and cooling system has reduced airflow or there are bad odors or a musty smell
- There are visible signs of dirt, dust or other pollutants

### Reason

The cabin filter / in-cabin microfilter function like your furnace filter at home. They clean the air by trapping pollen, bacteria, dust and exhaust gases that may find their way into a vehicle's HVAC system. Dirty filters reduce your heating and cooling efficiency



## Front Wipers

### Item Description

Your Wipers should be inspected at each service interval and replaced when indicated.

Indicators shock replacement may be needed are:

- If blades are cracked, become misshapen or lose their flexibility
- If they do not wipe properly

Replacing your wiper blades when recommended enhances safety, increases visibility and reduces the chance of damage to your windshield.

### Reason



## Tire Balance and Rotate

### Item Description

Balancing the vehicles tires are necessary to make sure the proper weight of the vehicle is distributed to the proper tire. Tire rotation helps protect tires against uneven wear by moving the tire location on the vehicle. Most tires will exhibit some form of wear based on numerous factors including: wheel alignment, miles driven, driving style and habits, and tire location on the vehicle. By moving or "rotating" the tires as recommended by the vehicle manufacturer, tires may wear more evenly; helping extend the life of the tires.

### Reason

If not properly balanced, a vehicle's tires can experience abnormal wear which can significantly decrease the life of the tire. If not done, you will experience vibration in the steering wheel at certain highway speeds. Also, vibration will occur in the seat or floorboard at certain highway speeds. Tire wear will become scalloped or cupped.



# Completed Repairs

PREPARED FOR  
**INVENTORY: 402569A**

Service Advisor  
Chris Howard (454)  
ckhoward785@gmail.com

**Date** 05/08/2024 07:39 AM  
2018 NISSAN ALTIMA  
**VIN** 1N4AL3AP7JC153103  
**Mileage** 137,466  
**RO#** 6075646

Service Name	Price
Engine Air Filter Replacement (I)	\$28.99
Cabin Filter & In-Cabin Micro Filter: recommended every 15,000 for that clean and fresh air can flow through the hvac system (I)	\$42.49
Front Wipers (I)	\$39.98
Tire Balance and Rotate (I)	\$49.95
Printed on May 08, 2024	
Quote expires on June 07, 2024	

Subtotal	\$161.41
Shop Charges	\$9.52
Tax	\$15.98
<b>Total</b>	<b>\$186.91</b>



**Capital City Nissan Of Topeka**  
1980 Sw Topeka Blvd  
Topeka, KS 66612

(785)267-6700