



Capital City Nissan Of Topeka

Automobile Status Report

Prepared For



INVENTORY: 9371PA

2015 Nissan PATHFINDER

Date May 07, 2024

VIN 5N1AR2MM7FC701852

Mileage 149663

RO# 6075571



Service Advisor

Bailey Boswell

bailey.topekanissan@gmail.com

7852676700



Capital City Nissan Of Topeka

1980 Sw Topeka Blvd

Topeka, KS 66612

Capital City Nissan Of Topeka Service Commitment

Excellence at every turn... and every straightaway

Our dealership's primary goal is to satisfy every customer at every opportunity. You visit our service department regularly, and we have developed a number of ways to make your visit more comfortable and informative. We know that you want straight answers, and that's the only way we will deliver it to you.

We understand that your knowledge of your vehicle and its necessary repairs is probably not on par with the understanding that your technician has. In order to be sure that his findings and reporting is as clear and concise as possible, we use this Vehicle Information Booklet as a tool to help us communicate your vehicle's condition to you.

Our technicians are the most qualified to work on your vehicle. They have trained extensively, and partake in continuing education regularly to be sure that they are up to date on any changes and improvements handed down from the manufacturer. Our service advisors strive to make your experience with us a pleasant one. They are here to attend to your automotive needs as well as communicate effectively between your technician and you.

Please make yourself comfortable in our waiting area. Watch some TV, use your laptop with our free WI-FI access or just relax and enjoy the quiet. Our courtesy shuttle can take you shopping, to a movie or home if you prefer.

We appreciate your business and will continue to strive for excellence in everything we do for you.



Complimentary Multi-Point Inspection

RO# 6075571

INVENTORY: 9371PA

VIN 5N1AR2MM7FC701852

Advisor Bailey Boswell

Technician CODY MILLER

Created On 5/6/2024

Checked and OK at this time

May Require Future Attention

Requires immediate attention

ROAD TEST

- BRAKE OPERATION PASS
- ENGINE OPERATION PASS
- DRIVETRAIN OPERATION PASS
- TRANSMISSION OPERATION PASS

LIGHTS

- TAIL LAMPS FAIL
- HEAD LAMPS PASS
- STOP LAMPS PASS
- TURN SIGNALS FAIL, PASS
- SIDE MARKER LAMPS PASS
- LICENSE PLATE LAMPS PASS
- EMERGENCY FLASHERS PASS

UNDER HOOD

- BLOCK TEST PASS
- OIL CHANGE PASS
- STEERING LINKS PASS
- FLUID AT LEVELS PASS


FUNCTIONAL


- HORN PASS
- TIRES PASS
- LF 5
- RF 5
- LR 5
- RR 5
- SEAT BELTS PASS
- WINDSHIELD PASS
- PARKING BRAKE PASS
- WIPERS AND WASHERS PASS
- HEATER AND DEFROSTER PASS
- OIL STICKER, ALL VALVE STEM CAPS AND ALL MAINTENANCE LIGHTS RESET PASS
- BRAKE PAD MEASUREMENTS PASS
- LF 5
- RF 5
- LR 5
- RR 5



Additional Service Recommendations

In the process of inspecting your vehicle for safety and reliability, your technician **CODY M** made the following observations and recommends that you do the necessary repairs to resolve these issues.

 Red: requires immediate attention.

 Yellow: in need of attention soon.

"Nissan" - Fog Lights: drivers fog light is burn't out

Item Description

Your Fog Lights should be inspected at each service interval and replaced as needed.

Indicators replacement is needed:

- Your Fog Lights have dimmed; gotten foggy or burned out

Ensuring your High Beams are replaced when needed increases driver and passenger safety. Fog lights are located at the bottom of your front bumper, allowing a whole area of the road to be lit. Brighter Fog Lamps increase your driving visibility at night and during adverse driving conditions such as fog and snow.

Reason



[Other]: rear drivers reverse light burnt out

Item Description

Speak with your service advisor for more information on this recommended service.

Reason



Bulb - License Plate Light: both license plate lights burnt out

Item Description

The lights for illuminating the license plate on the back and/or front of a vehicle.

Reason

If not replaced, you will fail the vehicle inspection and could receive a ticket for improper equipment.



License Plate Light

[Other]: antenna mast is broke recommend replacement

Item Description

Speak with your service advisor for more information on this recommended service.

Reason



Alignment: steering wheel slightly crooked to right

Item Description

Alignment is one of the key maintenance factors in getting the most tread life and performance from your tires. In addition, wheel alignment provides safe, predictable vehicle control as well as a smooth and comfortable ride that's free of pulling or vibration. Today's modern suspensions require a precise four-wheel alignment that can only be achieved through a modern alignment system. This applies to both front and rear wheel drive vehicles. Aligning a car or truck involves the adjustment of the vehicle's suspension, not the tires and wheels. The direction and the angles that the tires point in after the alignment is complete, however, are critically important. There are four factors involved in setting the alignment to specification: caster, camber, toe and ride height.

Reason



Alignment

If not done, you will see uneven or rapid tire wear, pulling or drifting away from a straight line, and wandering on a straight level road. It can also cause extra load on certain suspension components, making them more likely to fail.

[Other]: driver side headlight has a crack

Item Description

Speak with your service advisor for more information on this recommended service.

Reason



Front Wipers

Item Description

Your Wipers should be inspected at each service interval and replaced when indicated.

Indicators shock replacement may be needed are:

- If blades are cracked, become misshapen or lose their flexibility
- If they do not wipe properly

Replacing your wiper blades when recommended enhances safety, increases visibility and reduces the chance of damage to your windshield.

Reason



***Windshield Wiper Blade - (Rear)**

Item Description

Many vehicles are equipped with rear wipers; most commonly, sport utility vehicles, hatchbacks and

station wagons. The rear wiper allows the driver to have visibility through the rear window. This is important during bad weather or dirty conditions.

Reason

The rear windshield wiper will need to be replaced occasionally. When you notice the wiper streaking on the glass or becoming worn, remove it immediately and have it properly replaced.




Engine Air Filter Replacement

Item Description

The air filter prevents dirt and debris from entering the engine, which could otherwise cause premature engine wear.

Reason

If not replaced, poor gas mileage and premature engine wear will result.



Air Filter

Cabin Filter & In-Cabin Micro Filter:
Recommended every 15,000 miles to keep the mostly odor from flown through your fence Recommended every 15,000 miles to keep the mostly odor from flow through your vents

Item Description

Your Cabin Filter and In-Cabin Micro Filter should be inspected at each service and replaced every other oil change or after 12 months.

Your cabin and in-cabin micro filter may need replacement if:

- Your heating and cooling system has reduced airflow or there are bad odors or a musty smell
- There are visible signs of dirt, dust or other pollutants

Reason

The cabin filter / in-cabin microfilter function like



your furnace filter at home. They clean the air by trapping pollen, bacteria, dust and exhaust gases that may find their way into a vehicle's HVAC system. Dirty filters reduce your heating and cooling efficiency

Transmission Cooler Line: recommended rubber cooler line and clamp as it is leaking

Item Description

Transmission cooler lines deliver vital fluids to the transmission and all its internal components.

Reason

If the Transmission Cooler lines are not replaced when needed, the Transmission fluid that not only allows the gears to change but also prevents it from overheating cannot be properly delivered.



[Other]: rear front lower control arm due to not being able to adjust in the alignment

Item Description

Speak with your service advisor for more information on this recommended service.

Reason



Completed Repairs

PREPARED FOR
INVENTORY: 9371PA

Service Advisor
Bailey Boswell (764)
bailey.topekanissan@gmail.com

Date 05/06/2024 08:05 PM
2015 NISSAN PATHFINDER
VIN 5N1AR2MM7FC701852
Mileage 149,663
RO# 6075571

Service Name	Price
"Nissan" - Fog Lights: drivers fog light is burn't out (I)	\$63.80
[Other]: rear drivers reverse light burnt out (I)	\$54.69
Bulb - License Plate Light: both license plate lights burnt out (I)	\$30.99
[Other]: antenna mast is broke recommend replacement (I)	\$99.69
Alignment: steering wheel slightly crooked to right (I)	\$129.95
Front Wipers (I)	\$45.06
*Windshield Wiper Blade - (Rear) (I)	\$19.34
Engine Air Filter Replacement (I)	\$28.99
Cabin Filter & In-Cabin Micro Filter: Recommended every 15,000 miles to keep the mostly odor from flow through your vents (I)	\$31.46
Transmission Cooler Line: recommended rubber cooler line and clamp as it is leaking (I)	\$247.90
Printed on May 07, 2024	
Quote expires on June 06, 2024	

Subtotal	\$751.87
Shop Charges	\$30.00
Tax	\$73.10
Total	\$854.97



Capital City Nissan Of Topeka
1980 Sw Topeka Blvd
Topeka, KS 66612

(785)267-6700